





Success Hill emergency egress review

BLEMC – 5 May 2021







4 intersections with Lord St:


- Walter Road East
- Success Road (FMI)
- Anzac Terrace
- Railway Parade



- Walter Road East




- Success Road (FMI)




- Anzac Terrace



- Railway Parade



- Railway Parade



Potential actions:

- Walter Road East – remove fixed hand rail and replace with fold-down bollards (need to discuss how they would be managed day-to-day and in an emergency situation)
- Anzac Terrace – no change
- Railway Parade – no change
- Generally – develop information pack for residents within the precinct, advising of egress options

